

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2019

Submitted Date:

06/25/2019

Document Number:

696200314

FIELD INSPECTION FORM

Loc ID 410610 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 60890
Name of Operator: MOUNTAIN PETROLEUM CORP
Address: PO BOX 5043
City: BUENA VISTA State: CO Zip: 81211

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		mtnenergylock@gmail.com	
Lutz, Deborah		debbie.lutz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252474	WELL	PA	07/14/2008	GW	125-06349	BLACH 2-19	RI

General Comment:

This is a final reclamation and stormwater inspection.
This inspection is in response to Form 4 Sundry 402040705 "Final Reclamation Complete" and request for bond release.
Records show well PA 2008.
Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 252474 Type: WELL API Number: 125-06349 Status: PA Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% 20
 TRANSECT RESULTS OF REFERENCE AREA% 59
 TOTAL % OF DESIRABLE VEGETATION COVER 34
 VEGETATIVE COVER FAIL

Comment:

This location does not meet reclamation regulations; insufficient vegetative cover. Transects were conducted indicating vegetation is not 80% of the surrounding reference area.

Transects over the well location indicates a desirable perennial vegetative cover of 34% to that of the reference area. Transects over the facility location to the west of the well indicates a desirable perennial vegetative cover of 29% of that of the reference area.

Both locations are predominantly bare and exposed soil (38% and 42%). The dominant vegetative species observed via transect was Bromus tectorum (18%).

Corrective Action:

Perform reclamation in accordance with COGCC 1000 series rules and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil. Once vegetation meets 1000 series standards, submit a Form 4 Sundry and a follow-up inspection will be scheduled. Continue to monitor and manage this site until Final Reclamation has passed.

Date **11/15/2019**

Overall Final Reclamation

Fail

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200315	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4860393
696200316	Transect data sheet	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4860394