

Inspection Photos

API: 05-073-06310

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 6/24/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos



Photo 2. View of vegetation cover. There is some desirable grasses establishing but also a lot of undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos



Photo 3. There is some bare areas with signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos



Photo 4. Facing southeast at the location. There are areas bare of vegetation and undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos




Photo 5. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019

Inspection Photos



Photo 6. Facing east at the surrounding undisturbed pasture. Vegetation consists of Blue grama, Buffalo grass, Sand dropseed, Sand sage, among others.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06310 | Date: 6/24/2019