

**Inspection Photos**  
**Location Name: Lindstrom 24-8-67 1H**  
**Location ID: 425165**



**Photo 1: PREVIOUS tank battery sign without emergency contact**



**Photo 2: CURRENT tank battery sign containing emergency contact**



**Inspection Photos**  
**Location Name: Lindstrom 24-8-67 1H**  
**Location ID: 425165**



**Photo 3: PREVIOUS photo of stained soil behind crude oil tank**



**Photo 4: CURRENT photo of stained soil removed**



**Inspection Photos**  
**Location Name: Lindstrom 24-8-67 1H**  
**Location ID: 425165**



**Photo 5: PREVIOUS photo of trash at head of pumpjack**



**Photo 6: CURRENT photo of trash removed**

**Inspection Photos**  
**Location Name: Lindstrom 24-8-67 1H**  
**Location ID: 425165**



**Photo 7: PREVIOUS photo of door of pump jack motor**



**Photo 8: CURRENT photo of door attached**



**Inspection Photos**  
**Location Name: Lindstrom 24-8-67 1H**  
**Location ID: 425165**



**Photo 9: Stained soil/equipment**

