







29.06.2018 11:40











O Investment Properties 6T-421, 6Y-241, 401 | 40.512307, -104.701195 | Photo of battery disturbance stabilized with road base.



29.06.2018 11:42



O Investment Properties 6T-421, 6Y-241, 401 | 40.512653, -104.700512 | Photo of background vegetation/surface cover (pasture grasses and unassociated industrial development).



29.06.2018 11:44