

Inspection Photos
Location Name: Leffler 1i-HZ Pad
Location ID: 425284



Photo 1: Location



Photo 2: Labeling not visible



Inspection Photos
Location Name: Leffler 1i-HZ Pad
Location ID: 425284



Photo 3: Labeling not visible



Photo 4: Labeling not visible



Inspection Photos
Location Name: Leffler 1i-HZ Pad
Location ID: 425284



Photo 5: Labeling on inside of berm



Photo 6: (South) Heater treator house with stored supplies/trash.



Inspection Photos
Location Name: Leffler 1i-HZ Pad
Location ID: 425284



Photo 7: Heater treater with supplies stored.



Photo 8: (North) Heater treater with supplies/trash

Inspection Photos
Location Name: Leffler 1i-HZ Pad
Location ID: 425284



Photo 9: supplies/trash inside north heater treator house.