

Sage Brush Hills II 4504

API: 05-103-07527

Inspection: 679704907



Photo 1. Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Sage Brush Hills II 4504  
API: 05-103-07527  
Inspection: 679704907

Gas leak



Photo 2. Well head gas leak.



Photo 3. Well head gas leak.

Sage Brush Hills II 4504

API: 05-103-07527

Inspection: 679704907



Photo 4. Battery sign.



Photo 5. Separator stack.