

Inspection Photos

API: 05-017-07697

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 7/25/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing south along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019

Inspection Photos



Photo 2. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019

Inspection Photos



Photo 3. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019

Inspection Photos



Photo 4. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019

Inspection Photos



Photo 5. Center of the location facing west.



Inspection Photos



Photo 6. Facing toward the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07697 | Date: 7/25/2019