

Inspection Photos

Location Name: FAULT ZONE 43-27

API#: 05-071-07461

INSP. #: 695101182



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: FAULT ZONE 43-27 FOLLOWUP #1

API#: 05-071-07461

INSP. #: 695101182



PHOTO 3: FORM 4 HAS BEEN SUBMITTED AND IS UNDER REVIEW. WELL IS BEING PRODUCED ON A VACUUM. WELL CANNOT BE PRODUCED ON A VACUUM WITHOUT AN APPROVED FORM 4 SUNDRY NOTICE. IMMEDIATELY STOP PRODUCING WELL ON A VACUUM. CA DATE 8/19/19.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources