

Inspection Photos

Location Name: Coal Gulch Federal 4-24

Location ID: 312663

Inspection Date: August 19, 2019



Photo #1 – Aerial view of the location (GISOnline Maps).



Photo #2 – Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Coal Gulch Federal 4-24
Location ID: 312663
Inspection Date: August 19, 2019



Photo #3 – View of day tank sign and open wildlife mesh.



Photo #4 – View of day tank sign.



Inspection Photos
Location Name: Coal Gulch Federal 4-24
Location ID: 312663
Inspection Date: August 19, 2019



Photo #5 – View of unused well protecting cage.



Photo #6 – Stained gravel and soil on the southeast side of the 95 bbl produced water tank.



Inspection Photos

Location Name: Coal Gulch Federal 4-24

Location ID: 312663

Inspection Date: August 19, 2019



Photo #7 – View of plastic bucket with oil in the bottom located west of the well.



Photo #8 - Inadequate berms around day tank south of well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Coal Gulch Federal 4-24
Location ID: 312663
Inspection Date: August 19, 2019



Photo #9 – View of dead bird inside of the mesh cover of the produce water tank.



Photo #10 – View of pit ID 119432.



Inspection Photos
Location Name: Coal Gulch Federal 4-24
Location ID: 312663
Inspection Date: August 19, 2019



Photo #11 – View of the two active leak locations.

