

Inspection Photos

Loc#426365

Operator: Sandridge

Inspection Number: 692401277

Inspection Date: 8/15/19





Photo#1:
Overview of Location to East; unused equipment, rutting, debris.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Peterson Ridge Loc#426365



Photo#2:
Overview of Location to Northwest; unused equipment, rutting, debris. .

August 15, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Peterson Ridge Loc#426365



Photo#3:
BMPs not installed along access road.



Photo#4:
BMPs not installed along access road.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Peterson Ridge Loc#426365