

Inspection Photos
Location Name: Duncan 3
Location ID: 313110



Photo 1. Overview of location taken facing east. Annual weeds present on location.