

Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 1: Wellhead Sign (backwards on fencing)



Photo 2: Wellhead/UNUSED EQUIPMENT



Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 3: Tank Battery Sign



Photo 4: Tank Battery



Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 5: Location



Photo 6: Hole in berm wall/Hole in base of berm



Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 7: Unused Equipment in Gas Meter House

