

Final Reclamation Inspection

October 9, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 318785

Inspection Document #: 697500701

Weld County, CO

NENE Section 6 T1N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 1. Google Earth aerial photo taken 10/9/2015 during active operations. Photo illustrates the well location and offsite tank battery location.

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 2. Google Earth aerial photo taken 5/31/2018, approximately 2 months after plugging operations. At the time of this inspection, equipment remains at the tank battery location.

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 3. Photo taken from the tank battery location.

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 4. Photo taken from the tank battery location, facing East. Operator has failed to remove all equipment, remove gravel and perform final reclamation activities at the tank battery location.

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 5. Photo taken from the well location, facing West. Operator has failed to properly recontour the well location.

Inspection Photos
Location Name: FLANIGAN #1
Location ID: 318785



Photo 6. Photo taken from the well location access road, facing West. Photo illustrates the access road has not been properly recontoured and vegetation is not growing throughout portions.