

# Final Reclamation Inspection

October 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 310711

Inspection Document #: 697500752

Weld County, CO

NENW Section 15 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SENA #15-25  
Location ID: 310711



**Photo 1.** Photo taken from the tank battery location, facing South. There appears to be a lack of crop growth throughout portions of the tank battery.



Inspection Photos  
Location Name: SENA #15-25  
Location ID: 310711



**Photo 2.** Photo taken from the tank battery location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: SENA #15-25  
Location ID: 310711



**Photo 3.** Reference photo taken east of the tank battery location, facing North. Photo illustrates the vegetative difference from a reference crop area vs the lack of growth observed at the tank battery.



Inspection Photos  
Location Name: SENA #15-25  
Location ID: 310711



**Photo 4.** Photo taken from the well location, facing North. There appears to be some bare patches at the well location.