

Inspection Photos

API: 05-071-06339

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 10/24/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06339 | Date: 10/24/2019

Inspection Photos



Photo 1. There is a dripping water leak from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06339 | Date: 10/24/2019