

Inspection Photos
Operator: BP America
Location/API #: 067-07464
Date: 10-24-2019



Photo 1. View of the southern project area from the southwestern edge facing eastward.




Photo 2. View of Russian knapweed infestation (blue arrows) within the southern fill slope. Approximately 1000 individuals observed.



Photo 3. View of trash/debris blown to the edge of the northern working area.



Photo 4. View of Russian knapweed infestation within the northern cut-slope. Areas with knapweed will require revegetation and stabilization after treatment.



Photo 5. View of unmarked rig anchor at the well pad entrance.



Photo 6. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with native grasses such as James galleta and forbs such as *Tetrandeum* sp.