

Inspection Photos
Location Name: Pappenheim 6-62-27
Location ID: 432657




Photo 1 – 6-62-27-0108BH – Wellhead

Photo 2 – 6-62-27-1609BH2

Inspection Photos
Location Name: Pappenheim 6-62-27
Location ID: 432657



Photo 3 – 6-62-27-1742BH2 – Pumping Unit



Photo 4 – Unmarked 1" Risers

Inspection Photos
Location Name: Pappenheim 6-62-27
Location ID: 432657




Photo 5 – Unmarked 1" & 2" Risers



Photo 6 – Unmarked 1" and 3" Risers

Inspection Photos
Location Name: Pappenheim 6-62-27
Location ID: 432657




Photo 7 – Unmarked 1” Risers



Photo 8 – Tank Battery Overview