

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402232806

Date Received:  
11/06/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 5 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Jessica Dooling

970-675-4122

jessica\_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700045

Inspection Date: 10/16/2019

FIR Submit Date: 10/30/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 316678

Location Name: YELLOW CREEK-61S98W Number: 2NWSE County: \_\_\_\_\_

Qtrqr: NWSE Sec: 2 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991300 Longitude: -108.355590

FACILITY - API Number: 05-103- -00 Facility ID: 316678

Facility Name: YELLOW CREEK-61S98W Number: 2NWSE

Qtrqr: NWSE Sec: 2 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991300 Longitude: -108.355590

CORRECTIVE ACTIONS:

4 CA# 133117

Corrective Action: Comply with Rule 603.f .

Date: 11/06/2019

Response: CA COMPLETED

Date of Completion: 11/06/2019

Operator  
Comment:

Corrective action completed, trash removed from East side pf pad, see attached photo.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action completed, trash removed from East side of pad, see attached photo.

Thank you.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed: \_\_\_\_\_

Title: Regulatory Coordinator

Date: 11/6/2019 3:23:10 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402232821	20191106 Photo of Trash Removed From East Side of Pad
-----------	---

Total Attach: 1 Files