

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402237798

Date Received:
11/13/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jessica Dooling

970-675-4122

jessica_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700045

Inspection Date: 10/16/2019

FIR Submit Date: 10/30/2019

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 316678

Location Name: YELLOW CREEK-61S98W Number: 2NWSE County: _____

Qtrqr: NWSE Sec: 2 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991300 Longitude: -108.355590

FACILITY - API Number: 05-103- -00 Facility ID: 316678

Facility Name: YELLOW CREEK-61S98W Number: 2NWSE

Qtrqr: NWSE Sec: 2 Twp: 1S Range: 98W Meridian: 6

Latitude: 39.991300 Longitude: -108.355590

CORRECTIVE ACTIONS:

2 ☒ CA# 133115

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/14/2019

Response: CA COMPLETED

Date of Completion: 11/13/2019

Operator Comment: Stained gravel beneath tank man hatch removed, see attached photo

COGCC Decision: Approved

COGCC
Representative:

3 ☒ CA# 133116

Corrective Action: Install sign to comply with Rule 210.d.

Date: 12/30/2019

Response: CA COMPLETED

Date of Completion: 11/11/2019

Operator
Comment: Tank labels installed to comply with Rule 210.d, see attached photos

COGCC Decision: Approved

COGCC
Representative:

5 ☒ CA# 133118

Corrective Action: The operator shall complete a site investigation and determine the vertical aerial extent of impact within the footprint of the tank battery and all observed wet and stained areas outside of the tank battery. The operator shall submit a Site Investigation/Remediation Work Plan (F-27) within 14-days describing how the operator will complete the delineation of impacts and a schedule for the delineation.

Date: 11/13/2019

Response: CA COMPLETED

Date of Completion: 11/12/2019

Operator
Comment: Form 27 submitted 11/12/2019, DOC # 402235840, see attached

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corective actions have been copmpleted, please see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed:

Title: Regulatory Coordinator

Date: 11/13/2019 5:41:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402237798	FIR RESOLUTION SUBMITTED
402237834	20191112 YCF 2-35-1 Form 27 402235840
402237836	20191111 YCF 2-35-1 Tank Labeled photo
402237838	20191111 YCF 2-35-1 Tank Labeled photo_1
402237840	20191111 YCF 2-35-1 Tank Labeled photo_2
402237841	20191111 YCF 2-35-1 Tank Labeled photo_3
402238930	20191113 YCF 2-35-1 Gravel Removed from Hatch

Total Attach: 7 Files