

Inspection Photos
Location Name: North Platte /23-24
Location #: 310067



Colorado Oil & Gas Conservation Commission
40.3829, -104.38688, 1372.0m, 234°
11/20/2019 01:37:21 PM

Photo #1

North Platte 23-24 (05-123-25829) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.38387, -104.38751, 1370.0m, 138°
11/20/2019 01:52:39 PM

Photo #2

North Platte 23-24 Wellsite
Temporarily Abandoned | TA
Access road sign

Inspection Photos
Location Name: North Platte /23-24
Location #: 310067



Photo #3
North Platte 23-24, 24-24 Battery
Inactive | Shut-down