

Morning Activity Report

Entity: S8

FACILITY #8

Operator:

State ID:

API Number:

Map Reference Information

Weld, CO US

Map Description NNW sec 1-T1N-R67W
Unincorporated, CO 80621 USA

>>>Start: 11/08/2019 07:00 AM >>> End: 11/08/2019 03:00 PM Hours: 8

Type: Roustabout Report

Activity: Tank Battery Repair

Depth: 0

Day's Cost: 1,920.00

Accum Daily: 3,280.00

Budget:

Actual Cost:

AFE:

Tool Pusher:

Service Co: 09309

Company Rep:

Kauffman Well Service,

Remarks: Cleaned oil stains on culvert on inside of culver. Dumped VacMaster and washed out and put away.

Operator: Tony

Helper: Sid