

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2019

Submitted Date:

11/27/2019

Document Number:

699100645**FIELD INSPECTION FORM**Loc ID 306539 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289544	WELL	PR	06/12/2007	OW	123-24872	CONNELL C 4-29	TA

General Comment:[Snow covered ground.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or Emergency contact information at well.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	01/10/2020

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 289544 Type: WELL API Number: 123-24872 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A, Has Red "PTA" Variance Tag.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

COGCC Inspection Report Summary
 On 11/27/19 at approximately 0800 hrs, I, Inspector Adam Burns,
 Conducted an on-site inspection at Connell C 4-29 of Noble Energy, at
 API # 123-24872 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Sign not posted or Emergency contact information at well. Install sign to comply with Rule
 210.b.
 With a corrective date of 1/10/20.
 See attached photo.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.
 Continuing education inspections

User

burnsa

Date

11/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402249720	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999393
699100646	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999389