

Inspection Photos

Location Name: NAT'L HOG FARM-65N63W /9SWSW

Location #: 331096



Photo #1

Nat'l Hog Farm 14-9 (05-123-20147) Wellsite

Plugged & Abandoned | PA

~ 10 yds.

prior insp.



Photo #2

Nat'l Hog Farm 14-9 Wellsite

Plugged & Abandoned | PA

~ 10 yds.

Reclamation progressing

Inspection Photos

Location Name: NAT'L HOG FARM-65N63W /9SWSW

Location #: 331096



Photo #3

Nat'l Hog Farm 14-9 Battery site
Abandoned: Reclamation progressing
Unused Equipment
Gas meter run & riser
prior insp.



Photo #4

Nat'l Hog Farm 14-9 Battery site
Abandoned: Reclamation progressing
Unused Equipment
Gas meter run & riser: Removed