

Inspection Photos
Location Name: DF Ranch 10-22, 32 – Tank Battery
Location ID: 461759



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign



Inspection Photos

Location Name: DF Ranch 10-22, 32 – Tank Battery

Location ID: 461759



Photo 3 – Missing Capacity



Photo 4 – Water Tank – Missing Content, Capacity and NFPA Labels



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources