

# Inspection Photos

1/06/2020

Operator: DIAMOND BACK DRILLING &  
SUPPLY INC - 24120

Location ID: 398049

Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398049



**Photo 1:** Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Photos 1 and 4 also show cut slopes of the Location remains evident; Location does not appear to have been recontoured.



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398049



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources