

Inspection Photos

Operator: BP America
Location/API #: 067-09059
Date: 1-9-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Location is partially snow-covered, and grasses such as intermediate wheatgrass and crested wheatgrass are observable.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of large musk thistle in post-flowering condition, within the southern project area. Surrounding vegetation are annual weeds.



Photo 5. View of reference area, comprised of sagebrush shrubland vegetation.