

Inspection Photos
Location Name: Sheley TB
Location ID: 318143



Photo 1 TB signs

Photo 2 TB signs

Inspection Photos
Location Name: Sheley TB
Location ID: 318143



Photo 3 TB



Photo 4 Vertical separator

Inspection Photos
Location Name: Sheley TB
Location ID: 318143




Photo 5 Horiz.heated sep., Vert. sep




Photo 6 ECDs

Inspection Photos
Location Name: Sheley TB
Location ID: 318143



Photo 7 Compressor



Photo 8 Gas meter run, methanol tank