

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402296207

Date Received:

01/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

KIMBERLY MOLLENHAUER

Phone

9703045307

Email

KIMBERLY.MOLLENHAUER@NBLENERGY.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 699100932

Inspection Date: 01/21/2020

FIR Submit Date: 01/21/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 309991

Location Name: ELISE STATE C-64N64W Number: 24SENE County: WELD

Qtrqr: SENE Sec: 24 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.297963 Longitude: -104.494197

FACILITY - API Number: 05-123- -00 Facility ID: 295276

Facility Name: ELISE STATE C Number: 24-22

Qtrqr: SENE Sec: 24 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.297963 Longitude: -104.494197

CORRECTIVE ACTIONS:

1 ☒ CA# 136056

Corrective Action: "Properly treat or dispose of oily waste in accordance with 907.e." Comply w/ Rule 907.e.

Date: 02/11/2020

Response: CA COMPLETED

Date of Completion: 01/27/2020

Operator Comment: NOBLE REMOVED ALL OF THE CONTAMINATED DIRT AROUND THE WELLHEAD.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 136057

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/11/2020

Response: CA COMPLETED

Date of Completion: 01/27/2020

Operator Comment: Noble had GE go out to the wellhead and preform a full service on it on 1/22. They greased, and repacked the stem and body. It was checked after 5 days to make sure that there were no more leaks.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: KIMBERLY MOLLENHAUER

Signed:

Title: EHS TECH

Date: 1/28/2020 11:13:42 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402296207	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files