

# Construction and Stormwater Inspection

January 28, 2020

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 466299

Inspection Document #: 697501060

Weld County, CO

SWSE Section 25 T12N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 1.** Photo taken from the northeastern perimeter of location, facing North. Photo illustrates a berm and ditch BMP. The ditch BMP could be installed to a greater depth and more “V” shaped.

Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 2.** Photo taken from the northeastern perimeter of location, facing West. See comments under Photo 1 regarding the ditch BMP.



Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 3.** Photo taken from the northern perimeter of location, facing Southwest. Photo illustrates the stockpile to the right is topsoil and the stockpile to the left is of subsoil.

Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 4.** Photo taken from the topsoil stockpile, facing North. Photo illustrates there is some mixing of topsoil and subsoil. COGCC staff communicated to an Operator representative on location and on the phone, this observation and why topsoil should not be mixed.



Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 5.** Photo taken from the west-facing topsoil stockpile, facing North. Photo illustrates subsoil being mixed with topsoil. COGCC staff communicated to an Operator representative on location and on the phone, this observation and why topsoil should not be mixed. Operator should remove any subsoil from the topsoil.

Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 6.** Photo taken from the southwestern perimeter of location, facing South. Photo illustrates a sediment trap in-process of being installed.



Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 7.** Photo taken from the southern perimeter of location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 8.** Photo taken from the southeastern perimeter of location, facing East. See comments under Photo 6.

Inspection Photos  
Location Name: Fox Creek /25 SE  
Location ID: 466299



**Photo 9.** Photo taken from the southeastern perimeter of location, facing North. Photo illustrates a culvert installed in conjunction with the ditch BMP which is directed to a sediment trap.