

Inspection Photos

Location Name: WELL RANCH-USXAA-66N63W /35NENW

Location #: 306658



Colorado Oil & Gas Conservation Commission
40.44699, -104.40833, 1438.0m, 191°
02/01/2020 10:23:30 AM

Photo #1

Wells Ranch-USXAA 35-19 (05-123-25078) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.44711, -104.408, 1443.0m, 317°
02/01/2020 10:29:17 AM

Photo #2

Wells Ranch-USX BB AA 35-19,35-03,35-04,35-5,35-06
Battery site

Abandoned: All Equipment Removed

Reclamation progressing

*Formerly served Wells Ranch USX AA 35-14
(Plugged & Abandoned | PA)*

Inspection Photos

Location Name: WELL RANCH-USXAA-66N63W /35NENW

Location #: 306658



Colorado Oil & Gas Conservation Commission
40.44702, -104.40841, 1438.0m, 150°
02/01/2020 10:24:21 AM

Photo #3

Wells Ranch-USXAA 35-19 Wellsite

Unused motor oil drums / drip trays



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources