

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #1 MW-1 south of old soil storage pit

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #2 MW-3 east of tank battery

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #3 MW-4 west of old soil storage area

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #4 MW-4 west of old soil storage area

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #5 MW-2 North of old soil storage pit.

Inspection Photos
location 428531
Remediation Projects 14686
Inspection Date: 1/28/2020
Photos taken by Kris Neidel



Photo #6 MW-1 in foreground of photo.