

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/18/2020

Submitted Date:

02/20/2020

Document Number:

688000368**FIELD INSPECTION FORM**Loc ID 317229 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446492	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI
454306	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI
456489	SPILL OR RELEASE	AC			-	STATE 4 TANK BATTERY	EI

General Comment:

Inspected Facilities							
Facility ID:	446492	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI
Facility ID:	454306	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI
Facility ID:	456489	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: [Active Spill IDs 446492, 456489, 454306.](#)Corrective Action: [Provide the information required per COA on the above referenced spills. FI 688000196 indicates a CA date of 10/12/2018 for submittal of disposal manifests and soil sample analytical data for a minimum of four soil samples. Contact NE EPS with any questions regarding this CA.](#)Date: 03/27/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:Comment: [Open former oil skim pit excavation and soil stockpile on site.](#)Corrective Action: [Submit Form 27 for oil skim pit closure. Include soil disposal manifests and soil sample analytical data and soil sample location map as applicable.](#)Date: 03/06/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000369	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072962