

Inspection Photos
Location Name: UPV-66N63W /27SWNW
Location #: 330270



Colorado Oil & Gas Conservation Commission
40.45936, -104.43017, 1441.0m, 122°
02/28/2020 12:13:17 PM

Photo #1

UPV 27-5G3 (05-123-18780) Wellsite
Plugged & Abandoned | PA
~ 30 yds.
Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.46286, -104.42942, 1434.0m, 269°
02/28/2020 12:23:01 PM

Photo #2

Wells Ranch- USX AA 27-3 Battery site
Abandoned: All Equipment Removed
Reclamation progressing
Formerly served Wells Ranch USX AA 27-6, 27-19
UPV 27-4G3, 27-5G3
(Plugged & Abandoned | PA)