

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 1 –

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 2 – Oil impacted soil south of crude tanks being excavated

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 3 – Oil impacted soil north of crude tanks being excavated, view west

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 4 – Spill and impacted soil stockpile area north of crude tanks after excavation and stockpile removal

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 5 – Crude tank battery excavation of oil impacted soil

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 6 – Access road cleanup



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 7 – Pit ID 107531 – Rem #11676, view southwest

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 8 – Pit ID 107531 – Rem #11676, view west

Location Name: – Investment Equipment – Kincheloe Battery – Spill ID 470404
Inspection Date: 03/02/2020



Photo # 9 – Pit ID 107531 – Rem #11676, view north