

## Inspection Photos

Location Name: SGV 12H Pad & SHV 12H tank battery spill

Location ID: #312697 & Spill/Release ID: #473129

Inspection Date: March 13, 2020



Photo #1 – Sign at entrance to facility.



Photo #2 – View of tank battery from east.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: SGV 12H Pad & SHV 12H tank battery spill

Location ID: #312697 & Spill/Release ID: #473129

Inspection Date: March 13, 2020



**Photo #3 – View of south side of unlined earthen berm containment area.**



**Photo #4 – View of north side of unlined earthen berm containment area.**



## Inspection Photos

Location Name: SGV 12H Pad & SHV 12H tank battery spill

Location ID: #312697 & Spill/Release ID: #473129

Inspection Date: March 13, 2020



**Photo #5 – Damaged section of earthen berm outside of north wall.**



**Photo #6 – Overview of earthen berm containment area from northwest corner.**



## Inspection Photos

Location Name: SGV 12H Pad & SHV 12H tank battery spill

Location ID: #312697 & Spill/Release ID: #473129

Inspection Date: March 13, 2020



**Photo #7 – View of south side of earthen berm containment area.**



**Photo #8 – Unused, marked, and plugged flowline risers located southwest of separators.**

