

Inspection Photos

API: 071-08738

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/23/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 1. Facing northwest near the beginning of the access road. The road remains per approved 502b. Variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 2. This culvert is partially filled in with sediment and it appears stormwater is directed down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 3. Another culvert further along the road is filled in with sediment and it appears stormwater is directed down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 4. The vegetation is well established along the fill slope of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 5. Facing southeast at the beginning of the access road. Operator sign will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 6. This culvert near the location is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 7. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 8. Facing east along the fill slope. Vegetation is well established along fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 9. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 10. Facing toward the cut slope which appears to be stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020

Inspection Photos



Photo 11. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08738 | Date: 3/23/2020