



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 1, 2020 9:03:39 AM MDT
Server Receive Date:	Apr 1, 2020 9:06:46 AM MDT
Reference Number:	20200401-18138126159
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 1, 2020 9:02:38 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Mar 31, 2020
Well Name	JACQUEZ, THOMAS GAS UNIT B 1
API Number	50670746400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated Russian knapweed- beginning to see sprouting from root base



Photo of third corrective action completed



Completed work description of corrective action 3

anchor

Photo of fourth corrective action completed



Completed work description

Treated Russian knapweed on South side of location

Completed work description of corrective action 4

Treated Russian knapweed and downy brome

Additional photos



Additional photos





Completed work description  
Summary of all work completed

treated noxious weeds  
previous treatment dates 7/18/18, 5/15/19