

Inspection Photos
Location Name: Garcia #1
API: 05-067-07246



Notice of water line leak on well head LOTO.



Containment device around stuffing box.

Inspection Photos
Location Name: Garcia #1
API: 05-067-07246



Staining along access road.



Salt staining along edge of access road.

Inspection Photos
Location Name: Garcia #1
API: 05-067-07246



Stained vegetation beyond culvert on main road.



Staining apparent at head of impoundment. No standing water present.