

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Battery sign



Wellheads

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



VRT placards



Compressor vault placards and berm

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Chemical storage



Chemical storage

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Lube oil containment




Stained soil

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Stained soil



Stained soil

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Stained soil



Stained soil

Inspection Photos
Location Name: Haley Pad
Location ID: 318870



Stained soil



Stained soil