

**Inspection Photos**  
**Location Name: Noland 1-15**  
**Location ID: 312904**



**Photo 1. Overview of location taken at entrance facing east. Disturbed bird flying away from pump jack nest(s).**



**Photo 2. Close up of nest(s) in pump jack head.**