

# Interim Reclamation and Stormwater Inspection

May 5, 2020

Operator: NOBLE ENERGY INC- #100322

Location ID: 429887

Inspection Document #: 697501465

Weld County, CO

SESE Section 9 T4N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BETZ PC /G16-69HN  
Location ID: 429887



**Photo 1.** Photo taken from the eastern well location access road, facing West. Photo illustrates Operator has performed interim reclamation with the evidence of desirable plant species establishment. This area is currently being grazed by cattle. Interim reclamation will remain in-process due to some bare areas and not uniform establishment.

Inspection Photos  
Location Name: BETZ PC /G16-69HN  
Location ID: 429887



**Photo 2.** Photo taken from the eastern well location access road, facing Southwest. Photo illustrates the southern interim area. See comments under Photo 1.

Inspection Photos  
Location Name: BETZ PC /G16-69HN  
Location ID: 429887



**Photo 3.** Photo taken from the eastern well location access road, facing Northwest. Photo illustrates the northern interim area. See comments under Photo 1.

Inspection Photos  
Location Name: BETZ PC /G16-69HN  
Location ID: 429887



**Photo 4.** Reference photo taken from the south of well location, facing West. See comments under Photo 1.