

# *Inspection Photos*

*Loc#334693*

*Operator: Caerus*

*Inspection Number: 692402174*

*Inspection Date: 4/29/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

April 29, 2020





Photo#2:  
Interim reclamation and unmarked Anchor.

April 29, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Couey Loc#334693





Photo#3:  
Sediment movement and

Photo#4:  
BMPs needing maintenance.

April 29, 2020