

Inspection Photos
Location Name: Taylor 15-1
Location ID: 327562



Photo 1 – Tank Battery, WEEDS remain



Photo 2 – Heater Treater, WEEDS remain



Inspection Photos
Location Name: Taylor 15-1
Location ID: 327562




Photo 3 – Stained Soil at Loadline



Photo 4 – Stained Soil at Loadline

Inspection Photos
Location Name: Taylor 15-1
Location ID: 327562



Photo 7 – Pumping Unit, WEEDS remain



Photo 8 – Pit Area, WEEDS remain

Inspection Photos
Location Name: Taylor 15-1
Location ID: 327562



Photo 5 – Pumping Unit, WEEDS remain



Photo 6 – Pumping Unit, WEEDS remain

