

Inspection Photos
Operator: BP America
API#: 067-09088
Date: 5/12/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as sand dropseed, squirreltail, and sagebrush.



Photo 3. View of dense musk thistles within the southeastern project area. Approximately 150 individuals observed.



Photo 4. View of reference area vegetation comprised of open grass fields with crested wheatgrass and western wheatgrass, and sagebrush dominated shrubland.