

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 1. Overview of location taken facing east.



Photo 2. Erosion and weeds occurring on fill pile.



Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 3. Erosion and weeds on fill pile. Sediment moving under silt fence.



Photo 4. Erosion and weeds occurring on fill pile. Sediment moving under silt fence. Silt fence or other BMP not present on east end of fill pile.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 5. Erosion on cut slope.



Photo 6. Erosion on cut slope.