

Inspection Photos
Location Name: McCaw C #2
API: 05-067-08810



Northern edge of location.



Stained gravel near separator.

Inspection Photos
Location Name: McCaw C #2
API: 05-067-08810



McCaw C #2 pump jack.



Spill/Release Point ID #476264 point source near separator.