

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 468546



Photo 1 – Tank Battery



Photo 2 – Pit

Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 468546



Photo 3 – Tank Battery Sign – Emergency Contact Number not Legible



Photo 4 – Unmarked Risers at Tanks



Inspection Photos
Location Name: Green 1-7 Facility
Location ID: 468546



Photo 5 – Unmarked Riser at Heater Treater



Photo 6 – Stained Soil at Loadline on West Tank