

Inspection Photos  
Operator: BP America  
API#: 067-07136  
Date: 5/20/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing on the slope with grasses such as western wheatgrass and smooth brome.



Photo 3. View of stored materials in the southern project area.



Photo 4. View of more stored materials within the southern project area.



Photo 5. View of tractors and unused equipment within the southern project area.



Photo 6. View of reference area vegetation comprised of pinyon juniper woodland with understory of gambel oak, black sage, muttongrass, and penstemon.