

Inspection Photos
Location Name: Vawter 1-11-41-8-61
Location ID: 424144



Photo 1 – Tank Battery



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Vawter 1-11-41-8-61
Location ID: 424144



Photo 3 – Tank Battery sign does NOT reflect current Operator



Photo 4 – Pumping Unit Sign does reflect current Operator

Inspection Photos
Location Name: Vawter 1-11-41-8-61
Location ID: 424144



Photo 5 – Produced Water Tank missing Capacity and Content is fading

Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Vawter 1-11-41-8-61
Location ID: 424144



Photo 7 – Stained Soil at Exhaust