

Inspection Photos
Location Name: Fuqua 19-02-10-1H
Location ID: 324766



Photo 1. Overview of location taken facing south.



Photo 2. Two unlabeled containers at wellhead. Blue drum without secondary containment.

